

SERVO-TOP
QE5542

CE

Type

YA322SE

Instruction Manual

Part 3

QUICK-ROTAN Elektromotoren GmbH
Königstraße 154
67655 Kaiserslautern
Tel: 0631 / 200 38 80
Fax: 0631 / 200 38 62
E-Mail: tech.supp@quick-rotan.com
home: www.quick-rotan.com

www.promelectroavtomat.ru
English 2002-07-02

Contents Part 3

Chapt.	Contents	Page
11.	Survey and List of Parameters	11.1 - 11.6
11.1	Explanation of Parameter Survey	
11.2	Explanation of Parameter List	
11.3	Parameter Survey	
11.4	List of Parameters	
12.	Electrical Connections Diagram	12.1 - 12.4
13.	Maintenance and Repair	13.1

Technical updatings reserved!

11. Survey and List of Parameters

11.1 Explanation of Parameter Survey

The parameter survey is designed as an aid for finding parameters quickly. It is a summary of references for the parameter list. Listed behind each reference are all parameters which exert an influence on the function described by the reference.

The parameter survey is divided into five columns:

Column 1 shows the references (functions) to which parameters are assigned.

Column 2 shows the abbreviations of the respective functions.

Column 3 shows all parameters (setting numbers) belonging to the respective reference.

Column 4 shows, for each function (reference) which controls inputs or outputs, the applicable indications such as Ex or Ax which can also be found on the connections diagram.

Column 5 shows, for each function (control inputs (Ex) or control outputs (Ax)), the respective plugs with the number of contacts (see connections diagram).

Example for searching a parameter:

Keyword (function): inverse rotation

The parameter survey shows in column 3 the parameter numbers 618, 623, 801.

Suppose that the inverse rotation function is to be enabled. The parameter list shows this function under parameter number 618.

11.2 Explanation of Parameter List

The parameter list is divided into 5 columns. These comprise, in

column 1: the parameter number,

column 2: is the explanation (meaning) of the parameters and the coding system of row 1 of the keys of the mini operator's panel, used when the parameter concerned can be programmed with the mini operator's panel,

column 3: the programming level (A, B, C) on which the parameter in question can be accessed,

column 4: the range of values within which the parameter in question can be set,

column 5: the value of the parameter in question is set on delivery ex factory.

Parameters having "either/or" validity (software switches) can merely be set to value I or II. In the case of such parameters, column 4 is empty.

Parameter numbers in acute brackets; e.g. <105>, mean the value (content) set for the parameter in question.

Example:

107 Speed for front backtack when <106> = I

I limited by <105>

II limited by <607>

Explanation:

Parameter 107 is valid only the the value (content) of parameter <106> = I.

If parameter 107 is set to I (<107> = I), then the speed for the front backtack is limited by parameter 105, e.g. <105> = 1500. If parameter 107 is set to II (<107> = II), then the speed for the front backtack is limited by the value of parameter 607, e.g. <607> = 4000.

11.3 Parameter survey YA 322SE (2Z_Y04_1.HEX)

Function	Abbrev'n	Parameter	Input Output	Connection Socket/Contacts
Accelerate	DRZAN	722		
Affichage	ANZ	605		
Auxiliary drive	ZUSAN	805/808/809 892/893/899		
Band supply	BZUF	490		
Brake	DRZAB	723/851		
Control	REG	884/885/886 887/889/890 891/892/893 894		
Control of edge	KST	296		
Defect search	HWT	797		
Delay	VERZ	174/190/191 192/194/197 527/730/899 924		
Direction of rotation	DRR	800/805/808 809		
Display	ANZ	605		
Front backtack	AR	105		
Gather setting	RAFF	950/960		
Guiding aid	FUEGEH	923/924		
Hardware test	HWT	797		
Holder	TUPF	527		
Needle position	NAPO	700/701/702 703		
Number of stitches	STZA	128/131/132 133/141/174 294		
Photocell	LS	161		
Presser foot	PF	729/730		
Program	PR	128/131/132 133/851		
Programming level C	EBC	798		
Residual brake	STBR	718		

Soft start	SANL	116
Speed	DRZ	105/296/605 606/607/609 676/850
Speed decrease	DRZAB	723/851
Speed increase	DRZAN	722
Speed limitation	DB	676
Stacker	STAP	527/528
Start	START	161
Start delay	STVERZ	729
Stepper motor	SMOT	488/489/490 808/809/855 856/858/859 862/863/870 871/873/950 956/957/960 972/976/977
Stitch condensation	STVD	105
Thread monitor	FW	141
Thread trimming	SN	609
Time needed to switch on	EINZ	175/528/889
Transportation motor	TPM	592/593


11.4 List of Parameters YA 322SE (2Z_Y04_1.HEX)

No.	Function (Meaning)	Level	Range Values	of Value	Standard
105	(AR/DRZ/STVD) Speed for front backtack/stitch condensation	A,B,C	100 - 6400	3500	KI. 1
116	(SANL) Soft start stitches	A,B,C	0 - 255	6	KI. 1
128	(PR/STZA) Stitches for seam section 1	A,B,C	0 - 255	20	KI. 1
131	(PR/STZA) Stitches for seam section 4	A,B,C	0 - 255	6	KI. 1
132	(PR/STZA) Stitches for seam section 5	A,B,C	0 - 255	6	KI. 1
133	(PR/STZA) Stitches for seam section 6	A,B,C	0 - 255	6	KI. 1
141	(FW/STZA) Number of stitches until bobbin thread monitor signal becomes active (signal suppression on bobbin thread monitor)	B,C	0 - 255	0	KI. 1
161	(LS/START) Start delay for start of photocell	A,B,C	0 - 2550	800	KI. 1
174	(VERZ/STZA) Stitches until output Ax on	A,B,C	0 - 255	20	KI. 1
175	(EINZ) Time needed to switch on for output Ax	B,C	0 - 255	6	KI. 1
190	(VERZ) Delay t2	B,C	0 - 2550	60	KI. 1
191	(VERZ) Delay t3	B,C	0 - 2550	400	KI. 1
192	(VERZ) Delay t4	A,B,C	0 - 2550	1550	KI. 1
194	(VERZ) Delay t6	A,B,C	0 - 2550	2550	KI. 1
197	(VERZ) Delay t11	A,B,C	0 - 2550	850	KI. 1
294	(EINST/STZA) Einschaltzeit (Stiche) für die Schlitzkantensteuerung (SKS)	A,B,C	0 - 255	16	KI. 1
296	(DRZ/KST) Speed for control of edge	A,B,C	10 - 2550	200	KI. 1
488	(SMOT) reduction ratio for stepping motor 1	C	0 - 99	2	KI. 1
489	(SMOT) number of steps after stepping motor 1 zero position	B,C	0 - 100	30	KI. 1
490	(BZUF/SMOT) tape feed I via sensor II in sync with main drive	B,C	0 - 100	30	KI. 1
527	(STAP/TUPF/VERZ) Delay (ms) from stacker on to holder / stopper off	A,B,C	0 - 255	30	KI. 1
528	(EINZ/STAP) Duration (ms) of stacker function	B,C	0 - 2550	100	KI. 1
592	(TPM) Transportation motor quick	B,C	1 - 4	1	KI. 1
593	(TPM) Transportation motor slow	A,B,C	10 - 2550	400	KI. 1
605	(DRZ/ANZ) Actual speed in display I yes II no	B,C		I	KI. 1
606	(DRZ) Speed: level 1 (min.)	B,C	30 - 640	200	KI. 1
607	(DRZ) Speed: level 12 (max.)	B,C	100 - 10000	5800	KI. 1
609	(SN/DRZ) Trimming speed 1	B,C	30 - 300	200	KI. 1
676	(DRZ/DB) Speed adjustment via potentiometer possible I yes II no	B,C		I	KI. 1
700	(NAPO) Needle position 0 (reference position of the needle)	B,C	0 - 239	0	KI. 1
701	(NAPO) Angular adjustment I with handwheel (teach-in) II by keys (+/-)	B,C		I	KI. 1
702	(NAPO) Needle position 1 (needle down)	B,C	0 - 239	200	KI. 1
703	(NAPO) Needle position 2 (thread take-up lever up)	B,C	0 - 239	24	KI. 1
718	(STBR) Timing of residual brake (0 = brake off)	C	0 - 100	0	KI. 1
722	(DRZAN) Acceleration ramp 1 gradual 50 steep	C	1 - 50	45	KI. 1
723	(DRZAB) Brake ramp 1 gradual 50 steep	C	1 - 50	25	KI. 1


729	(STVERZ/PF) Start delay after lowering presser foot	B,C	0 - 2550	120	Kl. 1
730	(PF/VERZ) Lift delay for presser foot after seam end	C	0 - 2550	30	Kl. 1
797	(HWT) Hardware test	B,C		II	Kl. 1
	I yes				
	II no				
798	(EBC) Programming level C	B,C		II	Kl. 1
	I yes				
	II no				
800	(DRR) Direction of motor rotation viewed from belt pulley	B,C		II	Kl. 1
	I left-hand rotation				
	II right-hand rotation				
805	(DRR/ZUSAN) Rotational direction of auxiliary drive	B,C		II	Kl. 1
	I lefthand rotation				
	II righthand rotation				
808	(DRR/ZUSAN/SMOT) Rotating direction of stepping motor 1	B,C		II	Kl. 1
	I lefthand rotation				
	II righthand rotation				
809	(DRR/ZUSAN/SMOT) Rotating direction of stepping motor 2	B,C		II	Kl. 1
	I lefthand rotation				
	II righthand rotation				
850	(DRZ) Maximum motor speed	C		4500	Kl. 1
851	(PR/DRZAB) Brake ramp for stitch-count seams	C		I	Kl. 1
	I steep				
	II gradual				
855	(SMOT) maximum speed of stepping motor 2	B,C	100 - 9900	3000	Kl. 1
856	(SMOT) Start-/stopping speed of stepping motor 2	B,C	10 - 2550	350	Kl. 1
858	(SMOT) acceleration of stepping motor 2	B,C	1 - 255	5	Kl. 1
859	(SMOT) reduction ratio of main motor/stepping motor 2	B,C	0 - 99	2	Kl. 1
862	(SMOT) maximum current of stepping motor 2 (255 = 3.6 A)	B,C	1 - 255	160	Kl. 1
863	(SMOT) stationary current of stepping motor 2 (255 = 3.6 A)	B,C	0 - 255	70	Kl. 1
870	(SMOT) maximum speed of stepping motor 1	B,C	100 - 9900	2000	Kl. 1
871	(SMOT) Start-/stopping speed of stepping motor 1	B,C	10 - 990	500	Kl. 1
873	(SMOT) acceleration of stepping motor 1	B,C	0 - 255	4	Kl. 1
884	(REG) Proportional amplification of the speed control (in general)	C	4 - 50	13	Kl. 1
885	(REG) Integral amplification of the speed control	C	0 - 100	30	Kl. 1
886	(REG) Proportional amplification of the order controllers	C	1 - 50	20	Kl. 1
887	(REG) Differential amplification of the order controllers	C	1 - 100	30	Kl. 1
889	(EINZ/REG) Time required for order controlling (0 = always)	C	0 - 1000	200	Kl. 1
890	(REG) Proportional amplification of the superior order controllers for the residual brake	C	1 - 50	25	Kl. 1
891	(REG) Proportional amplification of the lower speed controllers for the residual brake	C	1 - 50	20	Kl. 1
892	(REG/ZUSAN) Proportional amplification of speed control for auxiliary drive	B,C	0 - 50	1	Kl. 1
893	(REG/ZUSAN) Integral amplification of speed control for auxiliary drive	C	0 - 100	4	Kl. 1
894	(REG) Rotational direction of motor and synchronizer	C		I	Kl. 1
	I different				
	II same				
898	(SONST) Number of motor poles	C		II	Kl. 1
	I 4 poles				
	II 6 poles				

899	(VERZ/ZUSAN) Delay of auxiliary drive	B,C	0 - 100	50	Kl. 1
923	(FUEGEH) guiding aid always on	A,B,C		II	Kl. 1
	I yes				
	II no				
924	(FUEGEH/VERZ) delay for guiding aid closure	B,C	0 - 2550	800	Kl. 1
950	(SMOT/RAFF) gathering value 1 of stepping motor axis 1	A,B,C	0 - 90	0	Kl. 1
956	(SMOT) maximum current of stepping motor 1 (255 = 3.6 A)	B,C	0 - 255	150	Kl. 1
957	(SMOT) stationary current of stepping motor 1 (255 = 3.6 A)	B,C	0 - 255	70	Kl. 1
960	(RAFF/SMOT) gathering value 1 of stepping motor axis 2	A,B,C	0 - 90	0	Kl. 1
972	(SMOT) number of stepping motor axes	B,C	0 - 3	0	Kl. 1
	0 none				
	1 one (only the first)				
	2 one (only the second)				
	3 two				
976	(SMOT) stepping motor 1 - mode	A,B,C	1 - 3	2	Kl. 1
	1 full step				
	2 half step				
	3 quarter step				
	4 eighth step				
977	(SMOT) stepping motor 2 - mode	B,C	1 - 3	2	Kl. 1
	1 full step				
	2 half step				
	3 quarter step				
	4 eighth step				


12. Electrical Connections Diagram YA321SE




X5



X4




X1



M1

M1


X2.2



M1



S2.1

X2.2








M2



S2.2

X2**X3**

Bedeutung der Magnete bzw. Magnetventile, Taster / Meaning of magnets and/or solenoids and keys
 Signification des aimants resp. solenoides et touches / Significação dos imãs e/ou as solenoidas e teclas
 Significato dei magneti, delle valvole magnetiche e dei tasti / Significación de los imanes y/o los solenoides y pulsadores / Betekenis van de magneten resp. magneetkleppen, toetsen

S9		Start - stopp / start - stop / start - stop / arranque - paragem / start - stop / arranque - parada / start - stop
S14		Stopp / stop / stop / paragem / stop / parada / stop
S16		Start manuell / start manuell
S2.1		Lichtschranke für Referenzpositon des Schrittmotors 1 / reference position light barrier of the stepping motor 1 / barrière lumineuse du moteur pas à pas 1 / barreira luminosa do motor de passo 1 / cellula fotoelettrica del motore step 1 / fotocélula del motor de pasos 1 / foto-elektrische beveiliging van de stappen motor 1
S2.2		Lichtschranke für Referenzpositon des Schrittmotors 2 / reference position light barrier of the stepping motor 2 / barrière lumineuse du moteur pas à pas 2 / barreira luminosa do motor de passo 2 / cellula fotoelettrica del motore step 2 / fotocélula del motor de pasos 2 / foto-elektrische beveiliging van de stappen motor 2
M1		Bandantrieb / tape feed / transport de ruban / transporte de cinta / trasporto nastro / transportador de cinta / bandtransport
Y1 I max 100 mA		Stapler / stacker / empileur / empilhadeira / impilatore / apiladora / hefinstrument
Y2 I max 100 mA		Stoffführungsrolle am Apparat / material guide at the attachment
Y8 I max 100 mA		Transport anheben / lift transport
Y9 I max 100 mA		Presserfuß heben / presser foot up / pied presseur en haut / calcador em cima/ alzapiedino su / prensatelas arriba / drukvoet optillen
Y11 I max 100 mA		Presserfußdruck / presser foot pressure
Y13 I max 100 mA		Stoffabfall saugen / material waste vacuuming / aspiration de déchets / aspirar de descida / aspirare immondizie / aspirar de desechos / afval zuigen

Bedeutung der Magnete bzw. Magnetventile, Taster / Meaning of magnets and/or solenoids and keys
 Signification des aimants resp. solenoides et touches / Significação dos imãs e/ou as solenoidas e teclas
 Significato dei magneti, delle valvole magnetiche e dei tasti / Significación de los imanes y/o los solenoides
 y pulsadores / Betekenis van de magneten resp. magneetkleppen, toetsen

Y14 I max 100 mA		Kette saugen / chain vacuuming / aspiration de chaînette / aspirar de cadeia / aspirare catenella / aspirar cadeneta / zuigen van een ketting
Y15 I max 100 mA		Apparat-Verschluß / attachment lock
Y16 I max 100 mA		Tisch blasen / blowing table

13. Maintenance and Repair



!! Before starting maintenance or repair work, switch off the SERVO-TOP, separate the drive system from mains power (for instance by pulling out the mains plug) and wait for the motor to come to a complete stop.

General maintenance work must only be done by specially trained personnel paying close attention to the operating instructions.

The SERVO-TOP ist largely maintenance-free.

However, make sure to perform the following maintenance work:

Depending on the operating conditions, clean the drive system regularly, at least once a week, from any dust or lint. Make sure in particular that the ventilation louvres and cooling fins of the motor, especially the cooling fins between the motor and the control box, are perfectly clean (Fig. 13).




Fig. 13

Remove any threads caught on the synchronizer shaft or on the belt pulley and/or motor shaft.

Check if the drive system is perfectly secured to the stand and that the accessories (synchronizer on machine shaft, speed control unit on control box) are safely mounted in their respective positions.

Check the drive belt for any wear and for correct tension.
Incorrect belt tension can increase noise and vibrations.



When opening covers or removing parts, apart from those removable by hand, live elements can be exposed.
Connections can also be electrically live.

If you require to open the drive system before starting maintenance or repair work or before replacing any parts, disconnect the drive system from any and all power sources.

If maintenance or repair work on the open unit is unavoidable, this may only be done by qualified personnel familiar with the risks involved. Observe all regulations as per EN 50110.

There can still be capacitors carrying a charge in the power electronics system, even when the drive system has been disconnected from all power sources. To avoid injury by electrical shock, it is therefore essential to wait at least 10 minutes between mains power shutoff and opening the control box.

In order to protect semi-conductor components from overvoltage, use only high-resistivity measuring equipment when making checks on the control system.

Any repair or servicing work requiring skilled knowhow may only be done by qualified personnel authorized by Quick-Rotan.

We emphasize that in accordance with the product liability law we are under no responsibility for damages caused by our products if these are due to

- unqualified repair
- the use of components not authorized by us
- actions made by any persons not authorized by us.